





SUPPLEMENTARY QUALITY DOCUMENT	SQD 126
Vendor SQAR Requirements by Commodity	PAGE: 1 of 2 DATE 16 NOV 15 REV: K

Note: This document requires FAA notification for all revisions

Distribution Approval List

Department	Name	Signature
Quality Manager	Wallace Baker	
VP of Operations	Norm Bullinger	
Production Control Manager	Linda Winslow	 Linda D. Winslow 11-13-15
Engineering Manager	Scott McMurtry (acting Eng. Manager)	 Scott McMurtry 11/13/15

Revision History

Date	Revision	Designation	Modified by	Approved by
11/16/15	K	Updated header logo. Merged commodities with identical SQAR requirements for ease of organization and maintenance.	DF	W Baker
07/15/15	J	Changed logo in header; changed "Quality System Procedure" to "Quality Management System" in header; updated Distribution Approval List	DF	W Baker
12/03/14	H	Deleted Plant column from Distribution Approval List. Corrected website address. Added SQAR 69 to each commodity.	DF	W Baker
05/23/14	G	Added Production Control Manager to Approval List. Changed Commodity "Rings" to "Machined Components". For Commodity "Wood Boxes" added SQAR 68. For Commodity "Tooling" and "Calibration Services" added SQAR 42. Deleted Note at bottom of page 2. Add Commodity and Applicable SQAR for Testing Services.	DF	R Morrow
11/13/13	F	Reformatted document – moving Distribution Approval List and Revision History to beginning of document per procedure requirements.	DF	R Morrow
07/24/13	E	Added Commodity "Calibration Services" and applicable SQARs	Deric Fetner	Above List
07/19/12	D	Added 15 & 15A to commodities Compounds/Cements, Raw Cloth, and Fabrics. Format modification.	Deric Fetner	Above List
05/22/12	C	Split Fittings and Rings Split Compounds and Raw Cloth and Fabrics. Added Hardware, Coated Fabrics Products, and Tooling Updated Applicable SQAR's Fittings Added 19, 35, 36, 37 Rings Added 19, 35, 36, 37 Hardware Added 35,36	Ryan Watts	Above List
05/11/12	B	Added 65, 66, 67, 68 to fittings/fitting rings. Added 66, 67, 68 to Compounds/fabrics/raw cloth Added 66 to wooden boxes	Ryan Watts	Above List
06/22/11	A	Added 38A and 64 to fittings/fitting rings and compounds/Fabric/Raw cloth	Ryan Watts	Above List
10/18/10	NR	Initial Release	Brian Lee	Above List

SUPPLEMENTARY QUALITY DOCUMENT	SQD 126
Vendor SQAR Requirements by Commodity	PAGE: 2 of 2 DATE 16 NOV 15 REV: K

This document defines the SQAR requirements by commodity. SQAR requirements are in Supplementary Quality Document SQAR on Amfuel website <http://www.amfuel.com>

Commodity

Applicable SQARs

Machined Components Hardware Fittings	1, 2, 3, 4, 9, 10, 11, 15, 15A, 17, 18, 18A, 27, 28, 29, 33, 37, 38, 38A, 38B, 41, 42, 44, 45, 45A, 46C, 49, 49A, 50, 58, 59, 60, 61, 62, 64, 65, 66, 67, 68, 69
Compounds / Cements Raw Cloth Fabrics Coated Fabric Products	1, 2, 3, 4, 9, 10, 11, 15, 15A, 17, 27, 28, 29, 33, 37, 38, 38A, 38B, 42, 44, 45, 46C, 49, 50, 59, 60, 61, 62, 64, 65, 66, 67, 68, 69
Wood Boxes	1, 2, 10, 11, 27, 28, 42, 59, 61, 62, 63, 64, 66, 67, 68, 69
Tooling	17, 37, 42, 46C, 49, 50, 59, 64, 66, 68, 69
Calibration Services	2, 3, 17, 42, 47, 53, 54, 68, 69
Testing Services	1, 2, 3, 5, 15, 15A, 17, 53, 54, 59, 62, 64, 66, 68, 69